Water Pollution

- Any stormwater pollution controls that are altered during Contractor activities must be returned to full operating condition as soon as possible.
- Stormwater pollution controls shall be installed to ensure that stormwater flowing off the work site does not have a visible sheen or is contaminated with suspended solids.
- A South Dakota Stormwater Construction Permit must be obtained prior to start of work, if one
 or more acres will be disturbed.

Petroleum Product Management

 Work that results in the storage of petroleum products in containers with an internal capacity of 55 gallons or greater or the installation of oil-filled operational equipment with an internal capacity of 55 gallons or greater shall be reported to the ESH Department and secondary containment must be installed.

Spills and Spill Reporting

- Do not allow spills of regulated substances to migrate off site. The following can be used to prevent the spread of a spill: Drain Covers, Spill Kits, and the construction of Emergency Containment Berms.
- All regulated substance spills and leaks from equipment must be cleaned up immediately; contaminated soil must be containerized and replaced with clean fill material. The Contractor is responsible for disposal of the contaminated soil.
- Spill reporting to the ESH Department IS NOT required if the release is less than one gallon and is cleaned up without an impact to the environment. Reporting IS required if the release is greater than one gallon or if the spill can not immediately be cleaned up.

Waste Management

- All waste, both solid and hazardous, generated by the Contractor, and all obsolete, expired, or unused materials procured by the Contractor are the responsibility of the Contractor, including the cost of disposal. The Contractor shall manage and dispose of all wastes generated in compliance with all applicable state and federal laws and regulations.
- The Contractor shall minimize, to the extent practical, the generation and accumulation of waste during the lifespan of the project.
- Waste shall not be allowed to accumulate to the point of becoming a threat to the environment (air, land, water) and must not be stored on the ground for longer than a single work shift.
- Do not dispose of industrial waste, chemicals, etc. into the sewer system or into underground workings or sumps.

Air Pollution

 Visible air emissions occurring from roads, stockpiles, conveyors, etc. used during Contractor work must be controlled by the Contractor.

Asbestos and PCBs

- Notify the ESH Department if you suspect a material may contain asbestos.
- Deliver legacy light ballasts and capacitors to the ESH Department.

Environmental Contacts:

Zach Adam, Environmental Coordinator zadam@sanfordlab.org

W: 605-571-2325 C: 605-389-0929 Bonita Goode, Environmental Manager

bgoode@sandfordlab.org W: 605-722-5030

C: 605-430-5969

Revision History

Rev	Date	Section	Paragraph	Summary of Change	Authorized by
01	10/11/2023	NA	NA	Initial Release	CCR 847