

Print 1

5 pages

WAREING MOTORS STURGIS

1 Ford Place Sturgis, SD 57785 (605) 347-3662



3

Services (1 of 5)

Review

Approve



Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES INSPECT AND QUOTE PRICE TO REPLACE 3 EACH TIRES (2 LEFT REAR, AND 1 RIGHT REAR INSIDE)

*Tires - 3: 255/70/r22.5

A tire is a round component made of rubber and reinforced with chords or belts made of several choices of materials. The tire is filled with air or nitrogen and surrounds a wheel's rim to transfer a vehicle's load from the axle through the wheel to the ground and to provide traction on the road's surface. With only four small contact patches between you and the road you want them to be as

Advisor Service Note

3/11/24, 2:07 PM ASR Portal 8

A tire is a round component made of rubber and reinforced with chords or belts made of several choices of materials. The tire is filled with air or nitrogen and surrounds a wheel's rim to transfer a vehicle's load from the axle through the wheel to the ground and to provide traction on the road's surface. With only four small contact patches between you and the road you want them to be as good as they can possibly be.

\$5,617.40

Add Service

Not today

Requested Service

Related requested service

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN



Needs immediate attention

Service was pre-approved

Add Service Not today

Quote Shows \$5,617.40, but that

15 not correct. They can guote 3

different tires=1@\$500

1@600 & estimate each

1@700

They are not able to work with these rims

so they would take it to a tire specialty shop

to be done.

1 1 1 Retual costs would be in a range of \$1,500 > 1,800 > \$2,100, for 3 tires. Plus disposal fees.



1 Ford Place Sturgis, SD 57785 (605) 347-3662

1

2

3

Services (2 of 5)

Review

Approve



Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN

Exhaust: replace

\$10,223.39

Add Service N

✓ Not today

extime conditions terms 8.14

Advisor Service Note

\$10,223.39

Add Service

Not today

Requested Service

Related requested service

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES PROVIDE ESTIMATE TO REPLACE BOTH ENGINE MOUNTS



Needs immediate attention

Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES PROVIDE ESTIMATE TO REPLACE BOTH ENGINE MOUNTS

Diagnostic: engine mountx2

Diagnostics when referred to in an automotive sense is



1 Ford Place Sturgis, SD 57785 (605) 347-3662





Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES PROVIDE ESTIMATE TO REPLACE BOTH ENGINE MOUNTS

Diagnostic: engine mountx2

Diagnostics when referred to in an automotive sense is the various testing done on the automobile to ensure safety and proper engine functioning. These tests are done with different sensors, computers and machines to establish a "cause and effect" relationship between what is working and what is not working with the automobile. The forms of diagnostics can range from brakes, to air conditioning, to

Advisor Service Note

\$1,548.30

establish a "cause and effect" relationship between what is working and what is not working with the automobile. The forms of diagnostics can range from brakes, to air conditioning, to suspension and many more.

\$1,548.30

Add Service

Not today

Requested Service

Related requested service

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES ESTIMATE FOR REPLACEMENT OF BROKEN MANIFOLD BOLTS



Needs immediate attention

Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES ESTIMATE FOR REPLACEMENT OF BROKEN MANIFOLD BOLTS.



1 Ford Place Sturgis, SD 57785 (605) 347-3662





Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES ESTIMATE FOR REPLACEMENT OF BROKEN MANIFOLD BOLTS

Exhaust Manifold Replacement: both sides

Exhaust manifolds are attached to the engine. Exhaust gases are expelled from each cylinder of the engine into the manifolds, where the gases are then released through the exhaust system at the rear of the vehicle. Exhaust manifolds are subject to extreme heat, which may cause them to warp or crack, necessitating their replacement.

\$3,677.76

Advisor Service Note

Exhaust manifolds are attached to the engine. Exhaust gases are expelled from each cylinder of the engine into the manifolds, where the gases are then released through the exhaust system at the rear of the vehicle. Exhaust manifolds are subject to extreme heat, which may cause them to warp or crack, necessitating their replacement.

\$3,677.76

Add Service

Not today

Requested Service

Related requested service

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES DIAGNOSE OIL LEAKS FROM ENGINE



Needs immediate attention

Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN



1 Ford Place Sturgis, SD 57785 (605) 347-3662





Service was pre-approved

[Primary]: GEN - GENERAL CONCERN: GENERAL CONCERN CUSTOMER STATES DIAGNOSE OIL LEAKS FROM ENGINE

Diagnostic - Oil Leak (Visual): seals

Diagnostics when referred to in an automotive sense is the various testing done on the automobile to ensure safety and proper engine functioning. These tests are done with different sensors, computers and machines to establish a "cause and effect" relationship between what is working and what is not working with the automobile. The forms of diagnostics can range from brakes, to air conditioning, to suspension and many more. This is the diagnostic

Advisor Service Note


\$5,539.64

3/11/24, 2:07 PM ASR Portal 8

Diagnostics when referred to in an automotive sense is the various testing done on the automobile to ensure safety and proper engine functioning. These tests are done with different sensors, computers and machines to establish a "cause and effect" relationship between what is working and what is not working with the automobile. The forms of diagnostics can range from brakes, to air conditioning, to suspension and many more. This is the diagnostic specifically used when looking for an oil leak.

\$5,539.64





extime CONDITIONS TERMS 8.14