

South Dakota Science and Technology Authority/
Sanford Underground Research Facility Lead, South Dakota

Oro Hondo Drive Replacement & Motor Rebuild

Addendum 2

Issued October 3, 2017

Change of Scope: Contractor will NOT be responsible for the relocation of an existing PLC panel to an adjacent wall that was stated in the RFP (Figure 2) page 3.